

ERROR : F0E6 F0E8 IGBT BREAKAGE
HOB NO WORK, RIGHT SIDE NO WORK, NO POT DETECTION:
SEE THE SERVICE BULLETIN IN DOCUMENTS

